

The fence that separates LTC Play area from ES football green

- Is nearing end of life
- There are several areas with rot within the fence
- Both Gates open the wrong way into the play area
- Potentially allowing access to roaming dogs
- Both gates close too fast
- Both have finger traps and are potential Guillotines
- Are two gates needed in such a short run of fencing?



Proposals and Costs

Option 1

- Replace complete fence with 1m high Galvanised roll top removed from Nightingale Road
- Fit one only new easy-gate™ soft close play area gate opening outward from the play area

Total Cost £4,456.22 +VAT



Proposals and Costs

Option 2

- Replace fence with new 1m high roll top galvanised fence.
- Fit one only new Easy-gate™ soft close play area gate opening outward from the play area

Total cost £6,124.49 +Vat

